

To be filled in by the Inspecting Officer


1	Name of officer	MILIMOL PHILIP		
2	Name of School	MARY MATHA PUBLIC SCHOOL KADAPLAMATTOM		
3	Location with name of Educational District / Sub District	Pala		
4	Classification of building as specified in column 4 of the application for fitness certificate and size			
	i Permanent	GF	1) 6.10x7.50x3.80	7 Nos
			2) 5.5x8.80x3.80	1 No
			3) 6.25x10.00x3.80	1 No
			4) 6.25x3.60x3.80	2 Nos
			5) 6.10x7.50x3.80	1 No
		FF	6) 6.10x7.50x3.80	7 Nos
			7) 6.25x6.80x3.80	1 No
			8) 10.20x12.10x3.80	1 No
		SF	9) 6.10x7.50x3.80	3 Nos
			10) 6.25x6.80x3.80	1 No
	ii Semi permanent	: NIL		
	iii Temporary shed	: NIL		
5	Period for which certificate is issued	: 2022-2023 Academic Year		
6	Nature of defects, if any			
	a Foundation and basement	: NIL		
	b Superstructure	: NIL		
	c Doors and windows	: NIL		
	d Wood work wrought and put up	: NIL		
	e Roof	: NIL		
	f Flooring	: NIL		
	g Miscellaneous(Cracks)	: NIL		
7	Any major defects noticed which will render the Building unsafe in any manner	: NIL		
8	Whether maintenance has been done properly	: Yes		
9	Whether the structure is sound or not for conducting classes	: Yes . Sound for conducting classes under normal wind and weather condition		

1) The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure to flood etc.

2) Any additional observations, if deemed necessary for the certificate may be furnished separately with the certificate

Certified that the school was inspected by me on 18.07.2022 and found to be fit to conduct classes for the period 2022-2023 Academic year

Kadaplammattom
18.07.2022



Signature :
Designation :

M. Milimol Philip
18/07/22
ASSISTANT ENGINEER
DISTRICT INSPECTION
KADAPLAMATTOM G.P.

